

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## AIRFRAME

Total Time Since New: 2.338,4 Hours (as of Mar/01/2020)  
 Total Landings Since New: 1.139 Cycles  
 Entry into service date September 24th 2008  
 Home Base Sao Paulo, Brazil  
 Program Coverage Smart Parts  
 Maintenance Tracking System

## ENGINES

|                         | Left Engine     | Right Engine  |
|-------------------------|-----------------|---------------|
| Description             | Honeywell AS907 |               |
| Total Hours Since New:  | 2.332,2 Hours   | 2.338,4 Hours |
| Total Cycles Since New: | 1.134 Cycles    | 1.139 Cycles  |
| Overhaul Due:           | 5.662 Hours     |               |
| Program Coverage        | MSP Gold        |               |

## APU

|                          |                      |
|--------------------------|----------------------|
| Description              | Honeywell GTCP36-150 |
| APU Total Time Since New | 1.859,25 Hours       |
| HSI Due/Overhaul Due     | On Condition         |
| Program Coverage         | MSP Gold             |

## MAJOR INSPECTION STATUS

|             |               |
|-------------|---------------|
| Inspection  | Next Due      |
| 2.400 Hours | October/2020  |
| 48 Months   | December/2020 |

## CONNECTIVITY

| Type of Unit              | Description        |
|---------------------------|--------------------|
| ICS 200 Iridium Telephone | Dual Phone handset |

## ENTERTAINMENT

| Type of Unit        | Quantity | Description                      |
|---------------------|----------|----------------------------------|
| Bulkhead Monitor(s) | Dual     | 15.1" Forward & Aft LCD Monitors |
| Airshow System      | Single   | Airshow 410                      |

## NAVIGATION & COMPLIANCE

WAAS  
 LPV

## INTERIOR

Number of Passengers Nine (9)  
 Galley Location Forward  
 Forward Cabin Configuration: Eight (8) executive club seats with foldout tables  
 Lavatory Location(s) Aft (Certified for Taxi, Take-off, Landing)  
 Galley Equipment: Coffee/Esspresso Maker Coffee maker, High Temp Oven

## EXTERIOR

Basic paint colors: white with blue and navy blue strips

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008




Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

## Bombardier Challenger 300 2008



Rogério Marques | [rogerio@flyairconsult.com](mailto:rogerio@flyairconsult.com) | 55.11.98889.3116 mob | 55.11.5055.5341 office

Av. Jamaris 100 | bl.C | cj. 905 – São Paulo | Cep: 04078-000

[www.flyairconsult.com](http://www.flyairconsult.com)

Na compra ou venda de sua aeronave, a AirConsult coloca a disposição mais de 35 anos de experiência no mercado. Nossa equipe de especialistas agrega competências que transformam complexos desafios em soluções. Nossa experiência e nosso conhecimento da indústria aeronáutica estão ao seu dispor para assegurar sempre os melhores resultados. Entre em contato e conheça o diferencial de qualidade da AirConsult.

Whether you're looking to buy an aircraft or sell one, AirConsult will put our 35+ years of experience to work in making it happen. When you turn to us, you're tapping into a great team of specialists that consistently transform complex challenges into solutions. Leveraging our market expertise and extensive industry partnerships to guarantee you'll always get the best advice, and the best deals. So give us a call and experience the AirConsult difference.